



Accoya Case Studies Revisited

Scottish Widows Building - Edinburgh

October 2008



the world's leading high technology wood

Photography October 2008



Photography 16th Dec 2010



Photography 16th Dec 2010



Photography 16th Dec 2010



Summary

- Over 2 years exterior use
- There's no sign of rot or decay
- Excellent coating performance
- No blisters or cracking
- Performs in extreme weather conditions
- Excellent colour retention